



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

August 25, 2005

Supervisor 10024

Mine Name: Three Mile 1
Operator Name: Mike Dettamanti

Permit number: S/025/013
Inspection Date: August 3, 2005
Time: 10:00

Inspector(s): Doug Jensen, Tom Munson, Dan Smith
Other Participants: None
Mine Status: Inspect

Weather: Warm, Cloudy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Site familiarization and to evaluate the site the possibility of closing the permit.

Inspection Summary:

5. Roads (maintenance, surfacing, dust control, safety)

The road into the site is not well defined; it is a maintenance road along side a fence. The road, which was never upgraded from a two-track access, is becoming overgrown due to lack of use.

7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)

The disturbance at the site was GPS'd which reflects a total disturbance of 0.59 acres. There is two small disturbances at the site. Neither of the areas was recontoured before the operator left the site.

10. Revegetation

Much of the site has become revegetated due to the encroachment of vegetation from the surrounding areas. It is felt that having the operator come back and recontour the site would destroy more vegetation than leaving the as it is at this time.


Inspection Date: August 3, 2005; Report Date: August 25, 2005
Page 2 of 2
S/025/013

Because this permit is located on BLM ground, a concurrence to this decision is needed from their office. A communication will be made with their office to see if they concur with this evaluation, or if they will require further work to be done before we can release the site.

Conclusions and Recommendations:

The Division will await BLM's decision before any decision is made regarding the closure of this permit.

Inspector's Signature




Date: 8/25/05

dj:jb

cc: Mike Dettamanti, Operator
Doug Powell, BLM, Grand Staircase Escalante National Park
Attachment: GPS

O:\M025-Kane\S0250013-ThreeMile1\inspections\08032005insp.doc



Mine Number: S250013
Mine Name: Three Mile #1
Township 40 S Range 06 W
Section 28 SLBM

Inspection Date Aug 3, 2005
Map Produced by DKS

Acres Disturbed	0.59
Acres Regraded	0
Acres Seeded	0


Total Acres Distrubed 0

Acres Reclaimed	0
Acres Excluded	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- | | |
|-----------------|---|
| County Boundary | Township or range Line |
| Access | Township or range line: location doubtful |
| Mine | Section line |
| NonMine | Section line: location doubtful |
| Other | Disturbed |
| Interstate | Regraded |
| US Route | Seeded |
| State Route | Reclaimed |
| Primary Route | Excluded |
| Secondary Route | Prelaw |
| Main Dirt Road | MinePermit |
| Unimproved Road | |
| Interchange | |
| Trail | |

DOQ imagery date 1998



0 625

Feet
Scale 1:7,500 (verify scale)
1 inch = 625 feet

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.